



TAS 2 do 8t

Označení	Nosnost		$\varnothing d / \varnothing d_1$	t / t ₁	t
	0°-45°	45°-60°			
	[t]	[t]			
TAS 2 - 6-8 t	1,6	1,12	18 / 13	180 / 54	100 / 25
TAS 2 - 8-8 t	2,8	2	20 / 16	180 / 70	100 / 34
TAS 2 - 10-8 t	4,25	3,15	22	180	100

TAS 2 do 16t

Označení	Nosnosti		$\varnothing d / \varnothing d_1$	t / t ₁	bi / b ₁
	0°-45°	45°-60°			
	[t]	[t]			
TAS 2 - 6-16 t	1,6	1,12	20 / 13	260 / 54	140 / 25
TAS 2 - 8-16 t	2,8	2	22 / 16	260 / 70	140 / 34
TAS 2 - 10-16 t	4,25	3,15	26 / 18	260 / 85	140 / 40
TAS 2 - 13-16 t	7,5	5,3	30 / 20	260 / 85	140 / 40
TAS 2 - 16-16 t	11,2	8	34 / 22	260 / 115	140 / 50

TAS 2 do 25t

Označení	Nosnost		$\varnothing d / \varnothing d_1$	t / t ₁	bi / b ₁
	0°-45°	45°-60°			
	[t]	[t]			
TAS 2 - 6-25t	1,6	1,12	22 / 13	340 / 54	180 / 25
TAS 2 - 8-25t	2,8	2	24 / 16	340 / 70	180 / 34
TAS 2 - 10-25 t	4,25	3,15	29 / 18	340 / 85	180 / 40
TAS 2 - 13-25 t	7,5	5,3	32 / 20	340 / 85	180 / 40
TAS 2 - 16-25 t	11,2	8	38 / 22	340 / 115	180 / 50
TAS 2 - 18-25 t	14	10	40 / 26	340 / 140	180 / 65
TAS 2 - 20-25 t	17	12,5	42 / 26	340 / 140	180 / 65

TAS 2 do 40t

Označení	Nosnost		$\varnothing d / \varnothing d_1$	t / t ₁	bi / b ₁
	0°-45°	45°-60°			
	[t]	[t]			
TAS 2 - 6-40t	1,6	1,12	24 / 13	430 / 54	220 / 25
TAS 2 - 10-40 t	4,25	3,15	30 / 18	430 / 85	220 / 40
TAS 2 - 13-40 t	7,5	5,3	34 / 20	430 / 85	220 / 40
TAS 2 - 16-40 t	11,2	8	40 / 26	430 / 140	220 / 65
TAS 2 - 18-40 t	14	10	42 / 26	430 / 140	220 / 65
TAS 2 - 20-40 t	17	12,5	45 / 26	430 / 140	220 / 65
TAS 2 - 22-40 t	21,2	15	48 / 32	430 / 150	220 / 70
TAS 2 - 26/28-40 t	33,5	25	54 / 40	430 / 170	220 / 80
TAS 2 - 32-40 t	45	31,5	62	430	220