



## TAS 3/4 do 8t

Označení	Nosnost		$\varnothing d / \varnothing d_1$	$t / t_1$	t	Váha
	0°-45°	45°-60°				
	[t]	[t]				
TAS 3/4 - 6-8 t	2,36	1,7	20 / 13	180 / 54	100 / 25	1,82
TAS 3/4 - 8-8 t	4,25	3	22 / 16	180 / 70	100 / 34	2,48

## TAS 3/4 do 16t

Označení	Nosnosti		$\varnothing d / \varnothing d_1$	$t / t_1$	$b_i / b_1$	Váha
	0°-45°	45°-60°				
	[t]	[t]				
TAS 3/4 - 6-16 t	2,36	1,7	22 / 13	260 / 54	140 / 25	2,77
TAS 3/4 - 8-16 t	4,25	3	26 / 18	260 / 85	140 / 40	4,52
TAS 3/4 - 10-16 t	6,7	4,75	30 / 18	260 / 85	140 / 40	5,68
TAS 3/4 - 13-16 t	11,2	8	34 / 22	260 / 115	140 / 50	8,00

## TAS 3/4 do 25t

Označení	Nosnost		$\varnothing d / \varnothing d_1$	$t / t_1$	$b_i / b_1$	Váha
	0°-45°	45°-60°				
	[t]	[t]				
TAS 3/4 - 6-25 t	2,36	1,7	24 / 13	340 / 54	180 / 25	3,80
TAS 3/4 - 8-25 t	4,25	3	29 / 18	340 / 85	180 / 40	6,25
TAS 3/4 - 10-25 t	6,7	4,75	32 / 18	340 / 85	180 / 40	7,30
TAS 3/4 - 13-25 t	11,2	8	38 / 22	340 / 115	180 / 50	11,15
TAS 3/4 - 16-25 t	17	11,8	42 / 26	340 / 140	180 / 65	14,97

## TAS 3/4 do 40t

Označení	Nosnost		$\varnothing d / \varnothing d_1$	$t / t_1$	$b_i / b_1$	Váha
	0°-45°	45°-60°				
	[t]	[t]				
TAS 3/4 - 6-40 t	2,36	1,7	26 / 13	430 / 54	220 / 25	5,42
TAS 3/4 - 8-40 t	IV.25	3	30 / 18	430 / 85	220 / 40	8,04
TAS 3/4 - 10-40 t	6,7	4,75	34 / 22	430 / 115	220 / 50	11,15
TAS 3/4 - 13-40 t	11,2	8	40 / 26	430 / 140	220 / 65	15,77
TAS 3/4 - 16-40 t	17	11,8	42 / 26	430 / 140	220 / 65	17,60
TAS 3/4 - 18-40 t	21,2	15	48 / 32	430 / 150	220 / 70	23,75
TAS 3/4 - 20/22-40 t	31,5	22,4	54 / 36	430 / 170	220 / 75	31,60
TAS 3/4 - 26/28-40 t	45	31,5	60 / 40	430 / 170	220 / 80	39,90