



TRH

Označení	Nosnost						Váha
		Ø d	a	m	c	t	
	[t]	[mm]					
TRH 8	0,13	8	28	23	15	64	0,07
TRH 10	0,2	10	36	30	17	78	0,13
TRH 13	0,35	13	46	40	20	96	0,27
TRH 16	0,6	16	50	45	24	114	0,43
TRH 18	0,75	18	56	50	27	128	0,70
TRH 20	1	20	64	55	30	144	0,90
TRH 30	2	30	80	72	45	198	2,90
TRH 36	3,15	36	104	90	60	262	5,38
TRH 50	5,3	50	140	120	75	338	14,50
TRH 60	8	60	160	135	90	398	24,00
TRH 70	10	70	166	138	105	443	36,60